Coach8 Information Sheet

Number 2
February 2026

10 / 27 South Pine Road, Brendale QLD 4500
P: 1300 253 464 E: educate@coach8.com.au

Timber Flooring, Moisture, and Equilibrium Moisture Content in Australian Climates

Abstract

Timber flooring is a hygroscopic material whose in-service performance is governed by moisture exchange with its surrounding environment. Liquid water exposure, ambient humidity, HVAC operation, and seasonal climate variation all influence timber moisture content and the resulting dimensional behaviour of timber floors. In Australia, where climatic conditions vary widely by region, these influences are particularly significant. This article examines the relationship between timber flooring and moisture through the concepts of equilibrium moisture content (EMC), anisotropic material behaviour, and regional climate effects. Practical approaches to moisture assessment are also discussed, drawing on guidance from the Australasian Timber Flooring Association and relevant industry standards, with the aim of improving understanding, risk management, and long-term flooring performance.

Keywords: timber flooring, equilibrium moisture content, EMC, humidity, Australian climate, moisture measurement, anisotropy

---

Timber flooring is a hygroscopic material whose in-service performance is governed by continuous moisture exchange with its surrounding environment. Liquid water exposure, ambient humidity, HVAC operation, and seasonal climate variation all influence timber moisture content and, in turn, dimensional stability and serviceability. In Australian buildings, where climate conditions vary widely by region, understanding how timber responds to moisture is fundamental to predicting movement, managing risk, and achieving durable flooring outcomes.

Timber continually absorbs and releases moisture in response to the temperature and relative humidity of the air to which it is exposed. It is also anisotropic, meaning its physical and mechanical properties vary with direction within the material. Moisture movement, shrinkage, swelling, strength, and stiffness differ when measured parallel to the grain, radially across growth rings, or tangentially to those rings. As a result, dimensional change in timber flooring is inherently non-uniform. Longitudinal movement is typically negligible, while tangential movement exceeds radial movement.

This directional behaviour explains why moisture-related changes manifest as cupping, crowning, gapping, or compressive stress rather than uniform expansion or contraction.

Cupping and crowning are driven primarily by moisture content gradients through the thickness of the board, rather than by absolute moisture content alone. Where the moisture content differs between the top and bottom faces of a flooring board, differential swelling or shrinkage develops across the thickness. If the underside of the board is at a higher moisture content than the exposed face, the board tends to cup, with the edges rising relative to the centre. Conversely, where the exposed face has a higher moisture content than the underside, the board tends to crown. The anisotropic nature of timber governs both the magnitude and direction of this deformation, as tangential swelling and shrinkage exceed radial movement, while longitudinal movement remains minimal. As a result, moisture gradients are relieved through curvature rather than uniform dimensional change, producing the characteristic cupping or crowning profiles observed in timber flooring.

Equilibrium moisture content (EMC) provides the conceptual framework for understanding this behaviour. EMC is the moisture content at which timber is in balance with the surrounding air at a given temperature and relative humidity. In occupied buildings, indoor conditions are not static; they fluctuate daily and seasonally in response to weather, occupancy, and building operation. EMC should therefore be understood as a dynamic condition rather than a fixed endpoint. Timber flooring continually adjusts toward equilibrium moisture content with the indoor environment it is actually exposed to. The concept of *expected in-service EMC* is used as a planning reference to anticipate long-term indoor conditions and manage timber movement, rather than to imply an active or intentional material response.

In practice, expected in-service EMC allows designers, installers, and specifiers to estimate the moisture content range a floor is likely to experience over time. Timber does not respond to intended design conditions; it responds only to actual exposure. Problems commonly arise when timber is acclimatised to temporary construction environments that do not reflect long-term indoor conditions, or when movement allowances are based on average values rather than seasonal extremes.

Guidance published by the *Australasian Timber Flooring Association* identifies practical ranges for average in-service timber moisture content. Dry internal environments are typically associated with moisture contents in the order of 8–10%, normal environments with approximately 10–12.5%, and moist environments with around 12.5–15%. [1] These ranges are not prescriptive limits; they are tools for anticipating behaviour. Their practical value lies in understanding the magnitude of movement that may occur within these bands and how that movement accumulates across a floor, particularly in wide boards or continuous floor expanses.

Acclimatisation of timber flooring is therefore conditional rather than automatic. Where the delivered moisture content of the flooring is already close to the anticipated in-service range, extended acclimatisation may provide little benefit and, in some cases, may increase risk if site conditions are unstable or unrepresentative. Effective moisture planning relies on accurate measurement of timber moisture content, appropriate species correction, and a realistic assessment of the indoor humidity environment the floor will experience over time.

Building operation plays a significant role in shaping indoor EMC. Heating systems commonly reduce indoor relative humidity during cooler months, while refrigerated air-conditioning and dehumidification can lower indoor moisture levels depending on system design, controls, and runtime. High solar-gain areas, such as rooms with extensive glazing or skylights, can experience localised drying, while intermittently occupied buildings or dwellings left closed for extended periods may develop atypical humidity profiles. These factors help explain why timber flooring may behave differently between rooms, between levels of a building, or between occupied and unoccupied periods.

Australia’s Climate Context and Its Influence on Indoor EMC

Australia’s diverse climate zones exert a strong and persistent influence on indoor humidity conditions and, by extension, the equilibrium moisture content of timber flooring. Regional climate establishes the boundary conditions within which buildings operate, shaping indoor relative humidity profiles even where mechanical ventilation and air-conditioning systems are present. While building design and operation can moderate indoor conditions, they do not eliminate the underlying influence of climate (Figure 1).



Figure 1. *Australian climate zones as defined by the National Construction Code created using climatic data from the Australian Bureau of Meteorology. These zones establish the external hygrothermal boundary conditions that influence indoor relative humidity profiles and, consequently, the equilibrium moisture content of timber flooring.*
Figure reproduced from publicly available material published by the Australian Bureau of Meteorology and/or the Australian Building Codes Board. Used for illustrative purposes only.

Recent observations published by the Australian Bureau of Meteorology indicate that large parts of Australia have experienced periods of above-average temperatures combined with wetter-than-average conditions across multiple climate zones. These conditions increase ambient moisture loads and can extend periods of elevated indoor relative humidity, particularly in buildings without continuous or well-managed humidity control. Such trends reinforce the importance of understanding EMC as a variable range rather than a fixed value and increase the likelihood of timber flooring trending toward higher in-service moisture contents during these periods.

Tropical and Subtropical Regions

In tropical regions of northern Australia, consistently high ambient temperatures and humidity dominate for much of the year. Outdoor air carries a high moisture load, and without effective air sealing and active dehumidification, this moisture readily migrates indoors. Indoor equilibrium moisture content in these regions typically sits toward the

upper end of common ranges, increasing the likelihood of expansion-related stresses in timber flooring.

The *Condensation in Buildings Handbook* notes that in warm, humid climates, moisture-related problems often arise not from bulk water ingress but from vapour transport driven by air movement and pressure differentials. Where cooled internal surfaces or materials fall below the dew point of incoming humid air, condensation may occur at interfaces or within building assemblies. These localised zones of elevated moisture can affect both timber flooring and subfloor systems, even in the absence of visible water entry.

Subtropical regions, including much of coastal Queensland and northern New South Wales, are characterised by pronounced seasonal humidity variation. Periods of high summer humidity are often followed by substantially drier winter conditions, producing larger annual swings in indoor EMC. Where HVAC systems are operated intermittently or are designed primarily for temperature control, these seasonal transitions can be amplified indoors. Such cyclic conditions increase the likelihood of intermittent condensation during periods of rapid temperature change, particularly in well-sealed and insulated buildings. For timber flooring, this environment increases the risk of both expansion during humid periods and shrinkage during drier seasons, placing greater importance on detailing that accommodates cyclical movement rather than a single average condition.

Temperate Regions

Temperate regions across southern Australia generally experience more moderate humidity levels and less extreme seasonal variation, but moisture-related risk remains. Winter heating commonly lowers indoor relative humidity, reducing EMC and promoting shrinkage, while cooler external temperatures increase the potential for condensation at poorly insulated or thermally bridged surfaces. The *Condensation in Buildings Handbook* emphasises that condensation risk in temperate climates is often driven by insufficient surface temperatures rather than high absolute humidity. Similar principles apply at floor level, particularly where timber flooring is installed over concrete slabs, suspended floors, or adjacent to unconditioned spaces. Seasonal drying and re-moistening cycles can therefore drive gradual dimensional change over time.

Arid and Semi-Arid Regions

In arid and semi-arid regions, low ambient humidity dominates for much of the year, resulting in low indoor EMC unless artificial humidification is introduced. In these environments, shrinkage, gapping, and checking represent the primary risks for timber flooring, particularly where timber has been supplied or acclimatised at moisture contents more typical of humid or temperate regions. While condensation risk is generally reduced in arid climates, rapid nocturnal cooling can still produce short-term

surface condensation where internal moisture sources exist. From a flooring performance perspective, excessive drying and restrained shrinkage remain the dominant concerns.

Implications Across All Climate Zones

Across all climate zones, building design, ventilation strategy, and HVAC operation can moderate indoor conditions but do not override regional climate influences. Moisture behaviour in buildings results from the interaction of climate, air movement, temperature gradients, and material properties. Timber flooring forms part of this system and responds accordingly. Localised microclimates—such as near external doors, glazing, wet areas, or poorly ventilated zones—can differ markedly from average indoor conditions, leading to uneven moisture distribution and differential movement within a single floor.

Measuring EMC and Assessing Moisture Conditions

Equilibrium moisture content cannot be measured directly; it is inferred by relating measured timber moisture content to ambient temperature and relative humidity. The Australasian Timber Flooring Association provides EMC reference data that correlate these ambient conditions with the moisture content timber will tend toward under stable conditions. In practice, ambient conditions are measured using a calibrated thermo-hygrometer and referenced against the ATFA EMC table (Figure 2), after which timber moisture content readings are evaluated relative to the estimated EMC.

Temperature	Moisture content at various relative humidities																		
°C	5%	10%	15%	20%	25%	30%	35%	40%	45%	50%	55%	60%	65%	70%	75%	80%	85%	90%	95%
0	1.4	2.6	3.7	4.6	5.5	6.3	7.1	7.9	8.7	9.5	10.4	11.3	12.4	13.5	14.9	16.5	18.5	21.0	24.3
10	1.4	2.6	3.6	4.6	5.5	6.3	7.1	7.9	8.7	9.5	10.3	11.2	12.3	13.4	14.8	16.4	18.4	20.9	24.3
20	1.3	2.5	3.6	4.5	5.4	6.2	7.0	7.7	8.5	9.3	10.1	11.0	12.0	13.1	14.5	16.0	18.0	20.5	23.9
30	1.2	2.4	3.4	4.3	5.2	6.0	6.7	7.5	8.2	9.0	9.8	10.6	11.6	12.7	14.0	15.5	17.5	20.0	23.4
40	1.1	2.2	3.2	4.1	5.0	5.7	6.4	7.1	7.9	8.6	9.4	10.2	11.1	12.2	13.4	15.0	16.8	19.3	22.7

Figure 2. *Representative equilibrium moisture content (EMC) chart expressed in metric units, illustrating the relationship between ambient temperature (°C), relative humidity (%RH), and timber moisture content (%). Charts of this type, as published by the Australasian Timber Flooring Association, are used to interpret measured timber moisture content relative to expected in-service conditions rather than as fixed acceptance criteria. Figure prepared for explanatory purposes.*

Accurate measurement of timber moisture content requires appropriate instruments and correct interpretation. ATFA guidance identifies resistance (pin-type) moisture meters as the preferred instrument for determining moisture content in timber flooring, as these meters provide depth-specific readings and allow for species correction. Capacitance (pinless) meters may be used as comparative or scanning tools but should not be relied upon alone to establish absolute moisture content values, particularly where surface finishes, adhesives, or underlying materials may influence readings.

Where timber flooring or sub-floor elements have been treated with preservatives, additional care is required when interpreting moisture meter readings. Electrical resistance–based measurements are influenced not only by moisture content but also by the ionic conductivity of the timber, which may be affected by preservative treatments and other soluble compounds. Building science research has shown that the electrical properties of timber under variable moisture conditions can be altered by the presence of dissolved ions, leading to apparent moisture contents that do not directly correspond to bound water content alone (BRANZ SR161). In such cases, moisture meter readings should be interpreted as indicative rather than absolute, with greater reliance placed on comparative measurements, environmental assessment, and manufacturer guidance. The presence of preservatives does not alter the fundamental relationship between timber moisture content and equilibrium moisture content, but it can affect the accuracy of electrical measurements if not properly accounted for.

These principles align with the guidance contained in *AS-IICRC S500 Standard for Professional Water Damage Restoration*, which addresses moisture measurement as part of broader moisture assessment practice. The Standard emphasises that moisture meters must be used by trained operators who understand meter limitations, calibration requirements, and appropriate applications. It recognises resistance-type meters as suitable for measuring moisture content in wood materials, while noting that capacitance meters are relative instruments intended for comparative evaluation rather than definitive moisture content determination.

Footnote

[1] Australian in-service equilibrium moisture content ranges are generally higher than those commonly referenced in North American guidance due to climatic and operational differences. Large areas of Australia experience warm, humid or seasonally humid conditions, with higher ambient moisture loads and longer periods of elevated relative humidity. In addition, residential buildings in Australia typically rely less on continuous winter heating and humidification than is common in colder North American climates, resulting in higher average indoor relative humidity. These factors

shift typical in-service EMC upward, particularly in tropical, subtropical, and coastal regions.

References

Australasian Timber Flooring Association (ATFA). (n.d.). Acclimatisation of solid tongue and groove timber flooring. ATFA Technical Information Sheet.

Australian Building Codes Board (ABCB). (2019). Condensation in buildings handbook. Australian Government, Canberra.

Australian Standard. (2025). AS-IICRC S500: Standard for Professional Water Damage Restoration. Standards Australia, Sydney.

National Wood Flooring Association (NWFA). (2020). NWFA wood flooring installation guidelines. National Wood Flooring Association, St. Louis, MO.

USDA Forest Products Laboratory. (2010). Wood handbook: Wood as an engineering material (General Technical Report FPL-GTR-190). U.S. Department of Agriculture, Madison, WI.

BRANZ. (2010). SR161: Moisture in timber. Building Research Association of New Zealand, Judgeford, New Zealand.